

• Roof Level_RF1 15893 RL 13978 • LEVEL 02 12070 • LEVEL 01 9910 ◆ LEVEL 00 6540 • LEVEL B1 3260 PROJECT DATUM


1 Proposed NE Elevation SCALE: 1:100


Proposed SW Elevation

SCALE: 1:100

Proposed SE Elevation

SCALE: 1:100





KEY PLAN

NO. DATE P01 21/10/2022 DC LRD Pre-App

St. Vincent's Hospital Fairview Redevelopment

PROJECT ADDRESS

St. Vincent's Hospital, Fairview, Dublin 3

St. Vincent's Hospital Fairview

19 Merrion Square, Dublin 2, Ireland Tel: +353 (0)1 669 3000
Email: mail@stwarchitects.com
Web: www.stwarchitects.com

P02

BROOKLAWN HOUSE - PROPOSED ELEVATIONS

SCALE @A1 ISSUED: 1:100 03/03/2023 DRAWN BY: CHECKED BY: Checker PROJECT ARCHITECT: PROJECT NO. DRAWING NO. REVISION

SVHF-STW-BH-ZZ-DR-A-024001

Copyright. All Rights Reserved. This work is copyright and cannot be produced or copied in any form or by any means (graphic, electronic or mechanical including photocopying) without the written permission of the originator. Any license, express or implied, to use this document for any purpose whatsoever is restricted to the terms of the agreement or implied agreement between the originator and the instructing party. Levels and contours are relative to an Ordnance Survey Datum

Figured dimensions in millimetres.

All drawings are to be read in conjunction with Architectural Specification.

LEGEND:

300mm wide French Drain

Aco / Linear slot drain

- Gulley to be unblocked
- New Gulley
- New RWP & Hopper Refurbished RWP & Hopper
- New cast iron guttering

New Window / Conservation Rooflight (Replaces existing unsuitable or irrepairable window)

Drawing to be read in conjunction with Carrig Conservation Report SVRD-CC-BH-ZZ-RP-Y-007

- This drawing shows principal renovations affecting the building only. The list below is not an exhaustive list. The above mentioned report details the extent of modifications and repairs to made in greater
- Render Render to be removed, open joints to be re-pointed and new rough cast render to be used as per Carrig Conservation
- All windows to be repaired, refurbished and re-painted as per Carrig Conservation report
- All redundant pipes, signage, wiring, fixtures and old lighting fixtures to be removed from the building elevations and roof as per Carrig Conservation report.
- 6. Rooflights to be replaced with new conservation rooflights
- Drainage Repair and upgrade rainwater drainage, including new French drains, new linear slot drains, unblocking of existing gullies, addition of new gullies and associated works, as per Carrig Conservation report.
- Remove all vegetation from and around the building and treat with herbicide where necessary, as per Carrig Conservation report.
- External surfaces, such as paving slabs, steps and stonework to be repaired and cleaned as per Carrig Conservation report.
- 10. Chimneys Refurbish chimney pots and stacks, including repointing and repairs and add ventilation cowls.
- Roofing Remove asbestos tiles and re-roof with new slate.
 Insulation, breathable membranes, new battens etc to be added as per Carrig Conservation report.
- 12. Guttering and Downpipes New cast iron guttering, downpipes and hoppers to be used where necessary and existing items to be refurbished and re-used where possible. Internal roof gutters to be refurbished. See Carrig Conservation report.
- 13. Doors refurbish and re-decorate all doors. Replace door furniture with suitable conservation brass hardware, as per Carrig Conservation report.

REVISION SCHEDULE

DESCRIPTION

14. Some re-pointing of external brickwork required - see Carrig Conservation report for details.